Precipitation Rate of Zirconia

(Volumetric Method)




FIG. 1

Zirconia Precipitation vs. Time KR 41B at Varying Concentrations (Volumetric Method)




FIG. 2

Precipitation Rate of Zirconia in Acetone KR 41B at Varying Concentrations (Mass Accumulation Method)




FIG. 3